

# Threading Diagram – Gammill® Premier (Non-Plus Model)



5. Insert thread up through the first hole, and back down through the third hole

9

8

5

3

2

10

7

4

6

11

12

2

1

6. Thread over the first "L" shaped post, down, then clockwise around the rotary tension (1 & 3/4 times), over the check spring and under the second post.

